
AIRAC MIL SUP 01/25 (MIL AD 4 EPTM)

Data publikacji / Publication date

26 DEC 2024

Obowiązuje od / Effective from

23 JAN 2025

Obowiązuje do / Effective to

31 DEC 2025 EST

PRACE REMONTOWE NA LOTNISKU TOMASZÓW MAZOWIECKI (EPTM)

W związku z trwającymi pracami remontowymi oraz złym stanem nawierzchni sztucznych wprowadza się następujące ograniczenia:

1. Lotnisko dostępne tylko dla śmigłowców.
2. RWY 29/11 zwężona do szerokości 40 m (10 m po obu stronach do linii centralnej RWY).
3. Prędkość kołowania ograniczona do 15 km/h.
4. TWY E1 oraz TWY E3 wyłączone z eksploatacji.

Patrz: załącznik graficzny.

Niniejszy Suplement zastępuje MIL SUP 21/24.

- KONIEC -

RENOVATION WORKS AT TOMASZÓW MAZOWIECKI (EPTM) AERODROME

Due to on-going renovation works and poor condition of artificial surfaces the following restrictions are introduced:


- The aerodrome is available only for helicopters.
- RWY 29/11 narrowed to a width of 40 m (10 m on both sides towards centreline of the RWY).
- Taxi speed limited to 15 km/h.
- TWY E1 and TWY E3 withdrawn from use.

See: graphical Appendix.

This Supplement replaces MIL SUP 21/24.

- END -

APPENDIX A



NOT TO SCALE